



| Number | Name             |
|--------|------------------|
| 1      | Cord             |
| 2      | Screw 4x16       |
| 3      | Right housing    |
| 4      | Protecting bush  |
| 5      | Switch           |
| 6      | Left chassic     |
| 7      | Wool washer      |
| 8      | Two tooth buckle |
| 9      | Stator           |
| 10     | 608 bearing      |
| 11     | Brush holder     |
| 12     | Carbon brush     |
| 13     | Bush cap         |
| 14     | Armature         |
| 15     | 608 bearing      |
| 16     | Gear             |
| 17     | Gear washer      |
| 18     | 6001 bearing     |
| 19     | Output shaft     |
| 20     | Chuck            |
| 21     | M5x18 screw      |